							150 140014			
		Room Number or				FACILITIES WORK	IEQ WORK ORDER			
Timestamp	Observation:	Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	ORDER NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT CLOSED
3/15/2018 8:39:25	obstructed (Wall, Ceiling)	120	Blocked vent	x				3/16/18		
3/15/2018 8:25:51	trash	131	could possibly fall	х				3/16/18	4/5/18	
3/15/2018 8:40:26	trash	120	up	x				3/16/18	4/5/18	
3/15/2018 8:47:19		129	closet	x				3/16/18	4/5/18	
3/15/2018 8:49:30 3/15/2018 9:01:20	trash	gym 126	close to ceiling	~	X			3/23/18 3/16/18	4/5/18	
3/15/2018 8:14:18	Stained, broken, holes,	Media	Cracked ceiling tiles	<u>^</u>	x			3/23/18	4/3/10	
3/15/2018 8:20:29	Stained, broken, holes,	451	Broken tiles		X			3/23/18		
3/15/2018 8:23:08	Stained, broken, holes,	Men's bath next to c1	Ceiling tile falling down		х			3/23/18		
3/15/2018 8:24:22	Stained, broken, holes,	131	Broken ceiling tiles		х			3/23/18		
3/15/2018 8:28:37	Stained, broken, holes,	104	Plastic on ceiling tile.		х			3/23/18		
3/15/2018 8:28:51	Stained, broken, holes,	104		х				3/16/18	4/5/18	
	Stained, broken, holes,	109	tiles.		х			3/23/18		
	Stained, broken, holes,	116	Broken ceiling tiles		х			3/23/18		
	Stained, broken, holes,	109	Ceiling light cover		X			3/23/18		
	Stained, broken, holes,	Girls bath next to c1 119	Damaged tile		x			3/23/18 3/23/18		
	Stained, broken, holes, Stained, broken, holes,	Cafe	Cracked ceiling tiles Cracked tile near kitchen		\$			3/23/18		
	Stained, broken, holes,	118	Cracked ceiling tiles		Ŷ			3/23/18		
	Stained, broken, holes,	117	Cord hanging out of tile		x			3/23/18		
	Stained, broken, holes,	153	shelf not 18 inches from	х	^			3/16/18	4/5/18	
3/15/2018 8:49:38	Stained, broken, holes,	123	Cracked ceiling tiles		х			3/23/18		
3/15/2018 8:50:44	Stained, broken, holes,	121	Cracked ceiling tiles		х			3/23/18		
	Stained, broken, holes,	Gym	Minor damage - monitor		х			3/23/18		
	Stained, broken, holes,	124	Cracked ceiling tiles		х			3/23/18		
	Stained, broken, holes,	126	Cord hanging from ceiling	1	х			3/23/18		
	Stained, broken, holes,	126	Cracked ceiling tiles	1	X		↓	3/23/18		
3/15/2018 8:18:52	Spotting, mildew, paint	Guidance file room	Rust on floor	1	x		<u> </u>	3/23/18		
3/15/2018 8:31:18	Spotting, mildew, paint	Boller room 129	should be monitored for Stained floor tiles in closet	1	×			3/23/18		
	Spotting, mildew, paint Evidence of humidity	129 Boys bath near gym	Stained floor tiles in closet Rust on ceiling grid	1	Ŷ		<u> </u>	3/23/18 3/23/18		
	FURNITURE AND	224	reaction cennig grid	×				3/23/18 3/16/18	4/5/18	
3/15/2018 8:14:51	FURNITURE AND	101	2 fabric chairs	x				3/16/18	4/5/18	
	FURNITURE AND	101	2 fabric chairs	x		1		3/16/18	4/5/18	
3/15/2018 8:24:29	FURNITURE AND	103		х				3/16/18	4/5/18	
3/15/2018 8:26:22	FURNITURE AND	103	fake plants	х				3/16/18	4/5/18	
3/15/2018 8:27:32	FURNITURE AND	130	alt Ed program	х				3/16/18	4/5/18	
3/15/2018 8:37:04	FURNITURE AND	119	Personal furniture	х				3/16/18	4/5/18	
	Stuffed animals, beanbags,	237	Stuffed animals need plan	х				3/16/18	4/5/18	
3/15/2018 8:12:27	Stuffed animals, beanbags,	224	Stuffed animals need plan	x				3/16/18	4/5/18	
3/15/2018 8:29:11	Stuffed animals, beanbags,	Outside of c2 107	Penguin	x				3/16/18	4/5/18	
3/15/2018 8:30:38	Stuffed animals, beanbags, Stuffed animals, beanbags,	107	Paper covering ceiling tile. light		x.			3/23/18		
	Stuffed animals, beanbags,	244	iigin	x	^			3/23/18	4/5/18	
	Stuffed animals, beanbags,	244	Non HCPSS carpet	x				3/16/18	4/5/18	
	Stuffed animals, beanbags,	113	Stuffed animals	x				3/16/18	4/5/18	
	Stuffed animals, beanbags,	113		x				3/23/18	4/5/18	
	Stuffed animals, beanbags,	112		х				3/23/18	4/5/18	
3/15/2018 8:43:40	Stuffed animals, beanbags,	112	Stuffed animals	х				3/16/18	4/5/18	
	Stuffed animals, beanbags,	Portable 46		x				3/16/18	4/5/18	
	or physical gaps around exit	130	ceiling		х			3/23/18		
3/15/2018 8:52:53	or physical gaps around exit	121	exterior door draft		х			3/23/18		
	MATERIALS/CHEMICALS:									
	Improperly stored or									
3/15/2018 8:24:58	marked	138 storage	Flaking paint		х			3/23/18		
	14. MATERIALS/CHEMICALS:									
	Improperly stored or		Closet closer to front door,							
3/15/2018 8:39:55	marked	FACS storage	18" of clearance needed		x			3/23/18		
	14.									
	MATERIALS/CHEMICALS:									
3/15/2018 8:42:59	Improperly stored or marked	Kitchen office	Missing and damaged fiberglass pipe insulation	1	x	1		3/23/18		1
	19. SINKS AND	· · · · · · · · · · · · · · · · · · ·	- grave p-pt instantion	1	Ľ	1		5420-10		
	FOUNTAINS: Drain slowly,			1	1					1
3/15/2018 8:22:10	work improperly, leak 19. SINKS AND	106			х			3/23/18		
	FOUNTAINS: Drain slowly,		A little dusty near fish	1		1				1
3/15/2018 8:22:31	work improperly, leak 23. ELECTRICAL:	106	tanks		х			3/23/18		
	23. ELECTRICAL:				I			-		
	Electrical outlets not secured, cover missing,			1	1					1
3/15/2018 8:14:03	frayed wires on equipment	Admin Conf. Room	Missing escutcheon Plate	1	х			3/23/18		1
	23. ELECTRICAL:									
	Electrical outlets not			1	1					1
3/15/2018 8:33:56	secured, cover missing, frayed wires on equipment	116	Cord cover broken	1	×	1		3/23/18		1
3, 13/2010 0.33:30	23. ELECTRICAL:			1				3123/18		
	Electrical outlets not			1		1				1
	secured, cover missing,									
3/15/2018 8:38:11	frayed wires on equipment 23. ELECTRICAL:	FACS Storage	Missing escutcheon plate	1	^		<u> </u>	3/23/18		
	Electrical outlets not			1		1				1
	secured, cover missing.			1		1				1
3/15/2018 8:45:18	frayed wires on equipment 24. ELECTRICAL CORDS:	129	Cord cover taped to floor	x				3/16/18	4/5/18	
	24. ELECTRICAL CORDS: Unsecured, extend across			1		1				1
	walkways, cord protectors			1	1					1
3/15/2018 8:47:14	not installed	153		1	х			3/23/18		
	24. ELECTRICAL CORDS:			1		1				1
	Unsecured, extend across walkways, cord protectors			1	1					1
3/15/2018 9:03:52	not installed	127	Unsecured cords	×	1			3/16/18	4/5/18	1
	31. VENTS/WINDOWS:				1					
	Blocked, shrubbery near			1	1					1
	vents or windows which	152	No vent covers	1	×			3/23/18		1
3/15/2010 0-40-07							1	3/23/18		
3/15/2018 8:49:07	hinder operation 31. VENTS/WINDOWS:	152								
3/15/2018 8:49:07	31. VENTS/WINDOWS: Blocked, shrubbery near	152								
	31. VENTS/WINDOWS: Blocked, shrubbery near vents or windows which									
3/15/2018 8:49:07 3/15/2018 8:49:15 3/15/2018 8:49:15	31. VENTS/WINDOWS: Blocked, shrubbery near	152 152 Portable 46	No covers for vent Ceiling fracking/peeling		×			3/23/18		